LAGRANGE et al.

Appl. No. 10/774,399

August 14, 2007

AMENDMENTS TO THE SPECIFICATION:

Please amend paragraph [0047] on page 14 of the specification as follows:

[0047] FIGURE 9 also shows that the termination of upper fillet 25 forms a 90.000° angle with the center line C through the bucket as denoted by angle C'. In FIGURE 10 angles D and E are measured from center line C to lines defined by points at which tangent lines along the first and second fillets and tangs, respectively, intersect. Angles D and E are respectively 18.000° and 25.780°. As shown in FIGURE 10, intersecting tangent lines T₁ and T₂ along the pressure faces of the bottommost tang do not lie on either line that forms the angle E of 25.78° with the center line.